

Netgear router FV338 firmware upgrades

For Netgear router firmware updates I recommend performing the following sequence at least twice in succession:

- 1) Upload the firmware update
- 2) Do a hardware reset (hold in small button with paperclip until lights flash)
- 3) Do a hard reboot with power switch (turn-off, let unit remain off for 30 sec. then turn back on).
- 4) Repeat step 1, 2 and 3

Afterwards manually re-enter in your configuration and re-apply every setting in the router at least twice whether you change it, or use it, or not. Then do a final hard reboot with the power switch...

Documents Posted on Netgear Forum by kpippen